

**UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
SUPERFUND SITE STRATEGY RECOMMENDATION - REGION 06**

Site Name: Doyle, Frank J. Transformer Site

CERCLIS ID#: TXD980865109

Alias Site Names:

Address:

305 E. Cottonwood Street

City/County or Parish/State/Zip Code:

Leonard, Fannin County, Texas 75452

Report Type, Date, and Author:

Screening Site Inspection Report, August 1998, TNRCC

RECOMMENDATION:

☒ **1. No Further Remedial Action Planned under Superfund (NFRAP)**

☐ **2. Further Investigation Needed Under Superfund**

☐ PA ☐ HRS ☐ SSI ☐ RA ☐ ESI ☐ RI/FS

To be performed by:

Other:

Priority: ☐ High ☐ Low

3. Action Deferred ☐ RCRA

☐ NRC

NOTIFY AUTHORITY:

☐ Removal

☐ SMCRA

☐ NRC

☐ UIC

☐ RCRA

☐ Remedial

☐ Resource Trustee

☐ SPCC

☐ TSCA

☒ State/Tribe

☐ CERCLA Enforcement ☐ Other

☐ CAA

☐ NPDES

☐ Federal Facility

SEND SSSR COPIES TO:

☐ 6SF-AC

☐ 6WQ-SP

☐ ATSDR

☒ State Agency ☐ Tribal Agency

DISCUSSION:

This site is an active salvage yard operation that receives and processes out of service power transmission transformers for recoverable metals. The site is .6 acres in size and is surrounded by a 6' high wooden fence. Processes include draining the oils from transformers into one of three storage tanks (1 x 375 gallon and 2 x 500gallon). The transformer cores are then pulled and placed in an oven to bake off the remaining oil, paper and varnish. The baked cores are then removed, cooled and stripped of all recoverable metals.

The pathways of concern at this site are soil and ground water. Extensive soil sampling was conducted both on and offsite. Elevated concentrations of polychlorinated biphenyls (PCB's) were found in widespread areas onsite and in a limited area offsite on the southern end of the facility. However there were no residences, day care centers, or schools within 200' of an identified area of observed contamination.

Three drinking water wells were sampled and based on the results it does not appear that the site has impacted any of these wells. Based upon the available information it does not appear that this site is a candidate for the National Priorities List (NPL) of federal Superfund sites. Therefore the site will be given the designation of "No Further Remedial Action Planned" (NFRAP). This will not preclude any future actions at the site by the State or other federal environmental programs.

APPROVALS:

910276



Report Reviewed by:

William

Rhotenberry/R6/USEPA/US

(Site Assessment Manager 6SF-RA)

☒ Approved

☐ Disapproved

08/22/2000

Disposition Recommended by:

☒ Approved

☐ Disapproved

(Team Leader 6SF-RA)

Disposition Recommended by:

☒ Approved

☐ Disapproved

(Deputy Branch Chief 6SF-RR)